

# DEWBOT VI Pit Checklist

## Performed at every pit break

Gloves are to be worn to move the robot!

1. Kicker in relaxed state
2. Battery change – used battery placed in charger
3. Classmate connected to charger
4. Bumper color check / replacement
5. Check / replace zip ties
6. Check / replace kicker bands
7. Check tire wear
8. Check wheel nuts & collars
9. Check connections – digital side car
10. Check air pressure (>80 psig needed)
11. Radio plugged in
12. Top secure
13. Gloves / Safety Glasses / Control Station
14. Scouting report – alliance meeting
15. Move to Arena
16. Clean Pit Area for the next cycle